## STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801

Telephone: (801) 538-5291 Fax: (801) 359-3940



## ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

1.	General Information		
	1.	Report Time Period: From (mo./yr.) $\frac{1/98}{1}$ To (mo./yr.) $\frac{1/99}{1}$	
	2.	DOGM File Number (Mine No): 5 /03本/047	
	3.	Mine Name: DOVE CREEK MILLSITE	
	4.	Mineral(s) Mined (or permitted to mine): NO MINE	
	5.	Type of mine	
	6.	Legal Description (Location of Lands Affected):	
	WK	<u>NW 1/4, NW 1/4, NW 1/4, Section 1Z</u> , Township 12 N, Range 15 W	
		1/4,1/4,1/4, Section, Township, Range	
		1/4,1/4,1/4, Section, Township, Range	
7.	Name	of Operator or Company: UTAH BUILDING STONE SUPPLY	
	8.	Permanent Street Address: 842 WEST 400 NORTH	
		City, State, Zip: WEST BOUNTIFUL, UTAH 84087	
		Phone: 801-295-0601	
	9.	Company Representative (or designated operator):	
		Name: WILLIAM BOWN	
		Title: PRESIDENT	
		Business Address: SAME AS * 8	
		City, State, Zip:	
		Phone:	
		☐ Please check if any of the above information has changed since previous year.	
II.	Mining	g and Reclamation	
	1.	Was there any mine related activity during the past year? Yes ☑ No □	
	2.	If no - what was the last year of activity?	
	3.	If yes - how much ore or mineral was mined?	

4.	Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.		
	FROM JULY THROUGH OCTOBER MATERIAL FROM		
	CLARK'S BASIN WAS BULKED HERE, AND PROCESSING PACKAGING,		
	WAS COMPLETED ONSITE. ALSO CREW LIVED ONSITE, INVENTORY		
	REMAINS ONSITE AS WELL AS PILES OF WASTE ROCK,		
5.	How much additional acreage was disturbed during the past year? 3.5 ACRES		
6.	How much acreage was reclaimed during the past year?		
7.	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.  FIRST YEAR OF USE, WE SIMPLY BEGAN DUMPING BULK LOADS AT  THE SOUTH END AND WORKED TO THE NORTH; DISTURBING APPROX.  3.5 ACRES		
	o y north		
8.	What is the total disturbed acreage of entire project at years end? 3.5 ACRES		
9.	Briefly summarize any mining and/or reclamation plans for the upcoming year.		
the second second second	PLANS ARE TO CLOSE OUT DOVE CREEK MILLSITE. ALL INVENTIORY		
	WILL BE REMOVED, TRAILERS, OUT-HOUSE, EQUIPMENT ALSO REMOVED.		
	WASTE ROCK BURIED AWAY PISTURBED AREAS		
	WILL BE RAKED, RESEEDED.		
NOTE:	Section III., "Additional Information" applies only to large mining operations.		
III. Additional Information			
1	An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.		
2.	Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.		
IV. Signature Requirement			
I here	by certify that the foregoing is true and correct.		
	Name (Typed or Print): WILLIAM L Bown		
	Title of Operator:  PRESIDENT		
	Signature of Operator: Lillam & Bows		
	Date: 2.1.99		
jb a:\forms\MR-AR			